Delta Shipyards

NPL Site Overview August 14, 2012



Aerial 1974

Houma, LA

165 acre area

Delta Shipyard was part of Delta Ironworks.

Sold to Chromalloy American Company in 1969

Sold in 1980 to Delta Services Industries of Houma.

Property purchased in 1986 by current owner

Site Background

- Delta Shipyard consisted of a cleaning and repairing facility for small cargo boats, fishing boats, and oil barges.
- The generated oils and wastewater were sent through a series of separation ponds, after which the oil was recovered and sold. Two pits were reported closed by LDEQ in 1984



Aerial 1989

4 Pits present in 78, are no longer present, site is no longer in operation.

EPA PA in 1981

LDEQ involvement with numerous violations throughout the 1980's

EPA ESI in 1997

Recommended for EE/CA by Site assessment in 1998

Site visit with LDEQ on January 10, 2012-LDEQ has asked for EPA assistance

Table 4-1
Delta Shipyard (CERCLIS ID LAD058475419)
On-Site Waste Sampling Results Significantly Above Background Concentrations

Analyte	Background Concentration		Characterization Sample Concentrations					
	Maximum Background	3 Times Maximum Background	Station Sample Date QC Type Depth	P01 P01-71-1 07/25/96 Normal 2.0'-3.0'	P02 P02-71-1 07/25/96 Normal 2.0'-3.0'	P03 P03-71-1 07/25/96 Normal 2.0'-3.0'	P04 P04-71-1 07/25/96 Normal 2.0'-3.0'	P05 P05-71-1 07/25/96 Normal 2.0'-3.0'
Volatile Organics								
Ethylbenzene (ug/kg)	ND			8700	3500	4500	660 J	8600
Toluene (ug/kg)	ND			2300 U	2100 U	3800	1700 U	6400
Xylenes (total) (ug/kg)	ND			27000	23000	28000	2000	56000
Semi-Volatile Organics								
2-Methylnaphthalene (ug/kg)	ND			390000	460000	470000	130000	410000
Naphthalene (ug/kg)	ND			130000	160000	160000	48000 J	130000
Phenanthrene (ug/kg)	32	96		91000 J	100000 J	110000 J	90000 U	61000 J C-BSQ
Pesticides								
Endosulfan II (ug/kg)	ND			84	88	89	44 U	62 U
Heptachlor epoxide (ug/kg)	ND			110	49	89	22 U	31 U
Polychorinated Biphenyls				35.				
No Parameters Above Background								
Metals								
Arsenic (mg/kg)	7.7	23.1		26.1	32.7	27.6	48.2	61.2
Cadmium (mg/kg)	ND			5.6	6.5	5.1	3.5	12.2
Chromium (mg/kg)	18.5	55.5		709	576	520	104	371
Cyanide (mg/kg)	ND			1.1	1.4	0.65	0.54 U	0.82 U
Lead (mg/kg)	117	351		861	952	771	520	561
Mercury (mg/kg)	ND			1.8	1.6	1.2	0.98	0.81
Sodium (mg/kg)	164	492		1330	1360	1980	1590	1200
Zinc (mg/kg)	206	618		1010	1140	1020	808	2160

Shaded Values Exceed 3 Times Maximum Background Concentrations for Constituents Attributable to the Site.

THIS DOCUMENT WAS PREPARED BY ROY F. WESTON, INC. EXPRESSLY FOR EPA. IT SHALL NOT BE RELEASED OR DISCLOSED IN WHOLE OR IN PART WITHOUT THE EXPRESS, WRITTEN PERMISSION OF EPA

What's in the Pits

PAH's

Volatiles

Metals

Pesticides

Past Surface Water Releases

Contaminant	Highest detected level	Type of benchmark	Benchmark level	Pathway	Optional: # wells or residences affected
Barium	26,300 mg/kg			Surface Water	- 24 7
Benzo(a) pyrene	4.1 mg/kg	Region 3 Freshwater Screening Sediment Value	0.15 mg/kg	Surface Water	
Zinc	10,200 mg/kg	Region 3 Freshwater Screening Sediment Value	121 mg/kg	Surface Water	
Fluoranthene	1.7 mg/kg	Region 3 Freshwater Screening Sediment Value	0.423 mg/kg	Surface Water	

Results are from releases documented in 1994 and 1997, additional samples from on-site sources and surface water has been conducted and results are pending.



Delta Today


Residences have built homes west of pit area

Pits are surrounded by woods, no fence

LDEQ would like to see the pits stabilized to prevent migration via gw, sw and direct human exposure

Site is located in a highly industrial portion of the intercoastal canal

Releases to ground water and surface water are likely occurring



Soil Investigation August 2012


Sludge in pits to 12'

Borings in drainage pathway had visible contamination

Borings along canal showed migration via groundwater

Visible contamination at the PPE

Analytical results pending



Surface Water Investigation

On-site wetlands are present along southern boundary

Fishing within the intercoastal canal

Visible contamination at PPE

Analytical results pending